

Airworthiness Directive: 107

Date: March 31, 1994

Subject: S-7 Courier Seat

Compliance: Mandatory

Models Effected: S-7 (0294128), S-7 (0294130) & S-7 (0792096)

The most forward position on the seat adjustment for the S-7 model will restrict the AFT movement of the control stick. To eliminate this problem, rivets should be installed as shown in the illustration.

